JKSimBlast History

31 January 2019

2DView v2.14.04, TimeHEx v2.14.04

- very minor fix in a startup error message

15 January 2019

2DBench v2.14.05, 2DFace v2.14.05, 2DRing v2.14.05, JKBMS v2.14.05

- minor fix in dongle license update

6 August 2018

2DRing v2.14.04

- modify paste process to look for data tables by heading instead of sequence in incoming data

25 June 2018

2DBench v2.14.03, 2DFace v2.14.03, 2DRing v2.14.03, JKBMS v2.14.03

- minor fix in dongle license check and version number

12 June 2018

TimeHEx v2.14.02

- uses default program license files License_THX.sbl and License_THX_NET.sbl, if present
- reads dongle license code, if present

8 June 2018

2DBench v2.14.02

- more on messages
- fixed minor license and dongle search issues

2DFace v2.14.02

- expanded startup warning messages
- fixed minor license and dongle search issues

2DRing v2.14.02

- expanded startup warning messages
- fixed minor license and dongle search issues

2DView v2.14.02

- fixed some missing license issues
- modify >Help >About
- new license file options: /LIC=filename and License_2DV.sbl file
- get license permits from dongle memory

JKBMS v2.14.02

- fixed error with expire date and runs from license file
- changes to >Help >About to display more info
- update and read license code in dongle memory

21 May 2018

2DFace v2.14.01

- fixed error interpreting some keystrokes, e.g. Ctrl+M in Surface mode created a node
- prevent surface delays from connecting automatically to relief holes

23 April 2018

2DBench v2.14.00

- expanded warning messages at startup

- optimise searches for network dongle

2DFace v2.14.00

- new function to upload license code to dongle memory
- read license details from dongle memory
- new command line switch /LIC to specify any license file
- new program-specific license file option License 2DF.sbl and License 2DF NET.sbl
- optimise searches for local, face and network dongles
- new command line switch /EXTRANET to search for network dongles N051 to N055 2DRing v2.14.00
- new function to upload license code to dongle memory
- read license details from dongle memory
- new command line switch /LIC to specify any license file
- new program-specific license file option License_2DR.sbl and License_2DR_NET.sbl
- optimise searches for local, face and network dongles
- new command line switch /EXTRANET to search for network dongles N051 to N055

27 March 2018

2DBench v2.13.39

- modified process in pasting Area data
- now searches for labels at start of each section
- ignores non-compliant lines
- search sequence:
- " AREA DATA"
 - to indicate that area data are present
- "Reference Point"
- get offset for Paste Relative
- "The Number of Lines/Labels"
- get number of point sets
- "Line/Label Data"
- start of points data
- "Line/Label Counter"
- get parameter data for current point set
- "POINTS"
- get points for current set
- repeat last two steps for each point set

6 March 2018

2DBench v2.13.38

- fixed some minor errors in license dates
- corrected "stuck" hole highlight in query

27 February 2018

2DFace v2.13.02

- fixed error in license check

2DRing v2.13.02

- fixed error in license check

JKBMS v2.13.02

- optimised search for database:
- will work with double-click on *.bms file

- can specify in command line, first item, precede with "/"
- added /LIC option

12 January 2018

2DBench v2.13.37

- set base expire date for different versions
- added specific program license file: License 2DB.sbl

29 November 2017

2DBench v2.13.36

- fixed error in updating license code for network dongle

24 November 2017

2DBench v2.13.35

- fixed error in saving blast to v3 text file

8 November 2017

2DBench v2.13.34

- license in dongle memory extended for network dongles
- updating license code from >Help >About requires access passwords

20 June 2017

2DBench v2.13.32

- read and update license in dongle memory
- if the dongle memory contains a coded license, program will use this instead of an external license file
 - will use default license file if no code present in dongle memory
 - can override to use external license file with /LIC command in shortcut, e.g.:
 - C:\Programs\JKSimBlast\2DBench\2DBench.exe /LIC=C:\Programs\JKSimBlast\temp_lic.nfo
 - can update license on dongle with [Update License] button on >Help >About

9 June 2017

2DBench v2.13.31

- modified old EVALUATION process from dongle memory to prevent conflict with new license on dongle

2DFace v2.13.01

- modified old EVALUATION process from dongle memory to prevent conflict with new license on dongle
- prevent potential crash caused by clipboard error from Excel with active copy/paste 2DRing v2.13.01
- modified old EVALUATION process from dongle memory to prevent conflict with new license on dongle
- prevent potential crash caused by clipboard error from Excel with active copy/paste 2DView v2.13.01
- modified startup setting of window size for current desktop space, fit beside JKBMS if running
- modified old EVALUATION process from dongle memory to prevent conflict with new license on dongle
- prevent potential crash caused by clipboard error from Excel with active copy/paste JKBMS v2.13.01
- modified old EVALUATION process from dongle memory to prevent conflict with new license

on dongle

- prevent potential crash caused by clipboard error from Excel with active copy/paste
- expanded debug file capacity

TimeHEx v2.13.01

- modified old EVALUATION process from dongle memory to prevent conflict with new license on dongle
- prevent potential crash caused by clipboard error from Excel with active copy/paste
- modified startup setting of window size and position for current desktop space
- tidied up glitches in writing parameters to TimeHEx.ini
- upgraded to run with Bench, Ring, Face and Net dongles, separate Net version no longer required

24 May 2017

2DBench v2.13.30

- prevent potential crash caused by clipboard error from Excel with active copy/paste

26 April 2017

2DBench v2.13.29

- in >Analysis >Contouring, increased line width in legend

28 February 2017

2DBench v2.13.28

- fixed an error where Energy Distribution units text did not change with selection

16 December 2016

2DBench v2.13.27

- changed behaviour of selection box and mask
- does not resize with [End] key
- does not change when other is selected from toolbar

15 December 2016

JKBMS v2.12.04

- modified Fragmentation graph
- change background colour, conflict with data colour
- added controls for pasting frag data from 2DBench, 2DRing, fixed error with size range from

JKFines

- user can enter name for frag data set
- tidied up controls and keys in Plan View for panning, zoom

18 October 2016

2DBench v2.13.25

- fixed an error in Query display with nearest hole empty

6 October 2016

2DBench v2.13.24

- see separate PDF file for more details
- Relief Rate analysis
- Energy Distribution and Damage Contours
- Open / Closed Polygons
- Query Display

- Hole Renumber
- JKSimBlast v3

1 April 2016

TimeHEx v2.01.00

- disabled check for Monte Carlo simulation in blast data, now works with any simulation results
- moved some buttons on toolbar

18 August 2015

2DBench v2.13.15

- Relief Rate analysis completed to a full working version, but some features and options yet to be done.

August 2015

JKBMS v2.12.03

- 3D viewer
- fixed error with display of multiple explosive decks and stem decks
- option to display decks in defined colours instead of holes
- option to set hole/deck enlargement
- option to set detonation and select colours
- fixed variable speed scale
- fix glitch with first hole still selected after detonation complete

28 July 2015

2DBench v2.13.14

- some minor changes and new analysis:
- partial complete of option to load any file as license by /LIC=filename
- new options on file menu for blast data in text files
- >File >Open from Text and >File >Save to Text
- new analysis feature for Relief Rate, not running in this version

1 November 2013

2DView v2.12.01

- update contact details in >Help >About
- change startup settings for grids, trimbox